



# Xserve G5 CD Drive Replacement

Today I will replace this little CD drive on my Xserve G5 guys ! And I will show you how to do !

Written By: alphaLONE



## INTRODUCTION

It's my first guide so hello fixers ! This Xserve G5 is the top of the top : Dual 2.7 Ghz PowerPC G5 from IBM, 2 GB DDR, 3x 80GB. But a sad day, the PSU died. That's all. So now, repair !

---



## PARTS:

- [Xserve G5 DVD drive](#) (1)
-

## Step 1 — CD/DVD drive



- Here's my dead Xserve G5. I need a new power supply for it. So he will serve for the demo.


## Step 2



- Unscrew the two screws.



## Step 3




- Remove the top of the server. You will have something like this.

## Step 4





- Hello little CD drive ! It's retirement time !

## Step 5



- Disconnect the cable.
- Push the little metal thing to the left to unsecure the CD drive.

## Step 6



- Push the drive
- Pull the drive.
- And finally, take the drive !

To reassemble your device, follow these instructions in reverse order.

